DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

MAJOR REPAIR AND ALTERATION [Airframe, Powerplant, Propeller, or Appliance)

Form Approved Budget Bureau No. 04-R060.1

FOR FAA USE ONLY
OFFICE IDENTIFICATION

		or type all entries. osition of this form.						LEAMING	thereof)
	MAKE				MODEL				
1. AIRCRAFT	BELLANCA				7ECA				
	SERIAL NO.				NATIONALITY AND REGISTRATION MARK				
	967-73 N-3					36349 *			
	\$184P / \$271								
2. OWNER	MASON LEWIS G				ADDRESS (As shown on registration certificate)				
					638 EDGEWATER LN				
*****		· · · · · · · · · · · · · · · · · · ·		3. FOR FAA USE ON	MOS	ES LAKE,	WA 98837		
				J. FUR FAR USE UN	ILT	<u> </u>			
	•			4					1,
	•								
	•	•			*				
•		**	•						
	2								
	<u> </u>	<u>4.</u>	UNIT I	DENTIFICATION					TVDF
UNIT	MAKE			WODEL				<u> </u>	TYPE
			MODEL SERIAL NO.				L NO.	REPAIR	ALTER-
				· · · · · · · · · · · · · · · · · · ·		-l		 	ATION
IRFRAME	***	*********	♥ (As. d	escribed in item 1 ah	oveleseee				1
	**************************************							xx	1
					· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·		
OWERPLANT			ĺ]			1
		\$,		l .
									L
ROPELLER		A							
						f ·			1
	TYPE								
•	ITPE							····	
PPLIANCE			1						
	MANUFACTURER								
			ļ						
			4	CONFORMITY STATEM	ENT	······································	L		
A. A	GENCY'S NAA	AE AND ADDRESS	<u> </u>		OF AGEN	107	T		
						4C1	C. CERT	IFICATE	NO.
MOORE, D	AN R			 			l		
6258 RD	3 N.E.			FOREIGN CERTIFIE		NK			
MOSES LAKE, WA 98837				CERTIFICATED REPAIR STATION			A&P 531	627811	
				MANUFACTURER					
). I certify t	hat the repair	and/or alteration m	ade to	the unit(s) identifi	ied in Item	التمد فعطه أد	المناب		
attachmen	ts hereto have	been made in according furnished herein is	dance w	vith the requirement	s of Part 4	of the U.S. I	ederal Aviation	ine reve in Ramil	te of
	miormation	furnished herein is	true a	nd correct to the be	st of my kr	owledge.			
TE				SIGNATURE OF AL	UTHORIZED	INDIVIDITAL			
	9, 1997				; · · - · · · · · · · · · ·				
MAY	- 1 2001			12 2.	2/00	- mg .		المو -	
MAY			APPRO	VAL FOR RETURN TO	CEDVICE	-			
MAY		. 7	ni i AV	IN ION NEIVAN TO	JERTICE			. <u> </u>	- /
ursuant to the	10 suchovies of	ren berenne16. J	1. 1						
utsuant to the	ne authority give	ren berenne16. J	below	the unit identified	in item 4 w	as inspected is	the manner	prescribe	d by
ursuant to the		7. ven persons specified eral Aviation Admini	below stration	the unit identified and is KAAPPRC	A DE L	DECIED			
ursuant to the Administra	T, STANDARDS	ren berenne16. J	below stration	13.22.00	, , , , , , , , , , , , , , , , , , ,	OTHER (Specify)			- 1 July 1
ursuant to the	T, STANDARDS	ven persons specified eral Aviation Admini		INSPECTION AUTHORIZA	TION	OTHER (Specify)	and the second of the second o		erita 1
ursuant to the Administrative FAA FI	T, STANDARDS	ven persons specified eral Aviation Admini MANUFACTURER		INSPECTION AUTHORIZA	TION	OTHER (Specify)			- Alexander
ursuant to ti	T, STANDARDS CTOR HESIGNEE	ven persons specified eral Aviation Admini		INSPECTION AUTHORIZATION OF TRANSPORT INSPECT	TION	OTHER (Specify)	and the second of the second o		or the state of th
arsuant to the Administrative FAA FI	T, STANDARDS CTOR HESIGNEE	ven persons specified eral Aviation Admini MANUFACTURER	xx	INSPECTION AUTHORIZA	TION C	OTHER (Specify)			

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. DESCRIPTION OF WORK ACCOMPLISHED (If more space is required, attach additional sheets. Identify with air-Egraft nationality and registration mark and date work completed.)

Removed right wing IAW Champion Aircraft 7ECA service manual Sec. 4-2. Removed fabric from the upper part of the right wing to the fourth (4th) inboard rib to access fuel tank. Repaired 1/2 crack in upper surface by welding IAW, AC 43.13-1A Chap. 2 Sec. 2 Par. 68 A(1), B, C, D, E, H, Fig. 2.1 & 2.2 also Chap. 14 Sec. 2 Par. 710 B, C. Passed fuel tank pressure test to 3.5 p.s.i. IAW FAR 23.965 (a) (1). Recovered with F.A.A. approved Poly-Fiber Stits© covering process IAW Chap. 2 (repair & refinishing fabric surfaces), applied; 3 coats Poly brush, 4 coats Poly spray, 2 coats Aero-thane Junuae white. Reinstalled right wing IAW Champion Aircraft 7ECA service manual Sec 4-15.

-N 36349 -

END DM

STATE OF THE STATE OF THE STATE OF