DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

MAJOR REPAIR AND ALTERATION

Form Approved Budger Bureau No. 04-R060.1 FOR FAA USE ONLY

for instruct	ions and dispo	sition of this form,	See Ph	R 43.9, FAR 43 Ap	pendix B, a	nd AC 43,9-1 (or äubäequen	t revision	i thereof
1. ÄIRCRAFT	I MANGE				MODEL	-	· · · · · · · · · · · · · · · · · · ·	 	
	BELLANCA SERIAL NO.				7ECA				
	967-73				NATIONALITY AND REGISTRATION MARK				
	NAME (As shown on registration certificate) MASON LEWIS G				N-36349 ". ADDRESS (As shown on registration certificate)				
2. OWNER									
					638 EDGEWATER LN				
				3. FOR FAA USE O	MI A	SES LAKE,	WA 9883	7	
					· · · · · · · · · · · · · · · · · · ·		<u> </u>		
•									*
		•				•			
. •		· ·						4	
								٠.	
			11111					4	
		<u> </u>	ONII I	DENTIFICATION	·			5	TYPE
UNIT	MAKE			MODEL		SERIAL NO.		<u> </u>	ALTER
								ŘEPAIR	ATION
IRFRAME	***	*********	¥ (As. di	escribed in Hem 1 ab	مممم امري				
	**************************************				O (#) # # # # # #	***		XX	1
OWERPLANT	-				······································	T .			
DALEKETWAI		e e		•		ŀ			
,									1
ROPELLER		.N.							
									1
	YPE								ľ
DRIANCE									<u> </u>
PPLIANCE -	AANUFACTURER		┪						•
								i	
			6.	CONFORMITY STATEM	ENT		·		-
A. AG	ENCY'S NAME	AND ADDRESS			OF AGE	NCY	C CT.	(111.0.1.0.1	
MOORE, DAN R				X U.S. CERTIFICATE				IFICATE	<u>NO, </u>
6258 RD 3 N.E.					TIPICATED MECHANIC				
*** ·				CERTIFICATED REPAIR STATION			A&P 531	627011	
				MANUFACTURER					
I certify the	at the repair a	nd/or alteration m	ade to	the unit(s) identified the the requirement	ed in item	4 above and	leséelhád as	د معد خالم	
and that the	information i	urnished herein is	lance w true an	the unit(s) identify the the requirement and correct to the be	s of Part 4:	of the U.S. P	deral Aviation	n Regul	rse or Atlons
TE					or or any are	iowiedke.			•
MAY 9	, 1997			SIGNATURE OF AL	HORIZED	INDIVIDUAL			
	. 1997			/ Jan.	2100	A	•	-	
		7.	APPROV	AL FOR RETURN TO	SERVICE			·····	
·		n persons specified	below.	the unit identified	In Itani 4 -	a luciario i s			
·	authority_give	allia malauta, "a a a a is		and is APPRO	VED R	as inspected in EJECTED	the manner	préscribé	d by
irsuant to the	authority give or of the Feder	d Aviation Adminis	tration						
rewant to the Administrate	BIMINAKNO	MANUFACTURER				OTHER (Specify)		·	· 李子 - 6
irsuant to the	BIMINAKNO		ХХ	INSPECTION AUTHORIZAT	IION S	OTHER (Specify)	. Jagain on a	To the figure of the control of the	e candianas.
irsuant to the Administrate	OR		XX	INSPECTION AUTHORIZAT	IION	OTHER (Specify)		To the figure of the control of the	e candianas.
FAA PLT.	OR	MANUFACTURER REPAIR STATION	ХХ	INSPECTION AUTHORIZAT CANADIAN DEPARTMENT OF TRANSPORT INSPECT OF AIRCRAFT	OR	OTHER (Specify)	. (September 1983) Total American medical American medical and the september 1981 (1981)	To Politica Participal	e candianas.
FAA FLT.	PIGNEE /AL OR	MANUFACTURER	XX	INSPECTION AUTHORIZAT CANADIAN DEPARTMENT OF TRANSPORT INSPECT	OR	OTHER (Specify)	Andrews and the second	To Politica Participal	e candianes. Anno de man

NOTICE

WELL WITH STATES Weight, and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

Identify with air-DESCRIPTION OF WORK ACCOMPLISHED (If more space is required, attach additional sheets. "scraft nationality and registration mark and date work completed.)

Removed right wing IAW Champion Aircraft 7ECA service manual Sec. 4-2. Removed fabric from the upper part of the right wing to the fourth (4th) inboard rib to access fuel tank. Repaired 1/2" crack in upper surface by welding IAW, AC 43.13-1A Chap. 2 Sec. 2 Par. 68 A(1), B, C, D, E, H, Fig. 2.1 & 2.2 also Chap. 14 Sec. 2 Par. 710 B, C. Passed fuel tank pressure test to 3.5 p.s.i. IAW FAR 23.965 (a) (1). Recovered with F.A.A. approved Poly Fiber Stits© covering process IAW Chap. 2 (repair & refinishing fabric surfaces), applied; 3 coats Poly brush, 4 coats Poly spray, 2 coats Aero-thane Junuae white. Reinstalled right wing IAW Champion Aircraft 7ECA service manual Sec 4-15.

-N 36349 ×

END DM

·精神 (2)

the posts to be

A CONTRACT OF

Vizi i

19.5